

# FIFTY-YEAR PLUME RESPONSE TO SUCCESSIVE REMEDIAL MEASURES EMPLOYED WITH AN EVOLVING SITE CONCEPTUAL MODEL

47th Annual Environmental Show of the South May 17, 2018
David Heidlauf, CPG



### **SITE ORIGIN**


- 1963 lower Mississippi River fish kill traced back to pesticide plant
- Plant forced to change waste disposal method
- Considered Gulf of Mexico disposal, incineration and land disposal options
- Plant made the following justification statement for land disposal

"Shallow burial of toxic waste is a timehonored procedure and it does not pose any real or immediate hazard to public safety."



# PESTICIDE WASTE DISPOSAL FROM 1964-1973











# **WASTE DISPOSAL AREAS**






# **SITE TIMELINE**






# SITE CONCEPTUAL MODEL - 1964 SITE DEVELOPMENT






### **1967 USGS STUDY**

- Evaluated the potential for pesticide groundwater contamination
- Stratigraphic information from vadose zone borings and one deep site well
- Easterly groundwater flow direction based on perched well data







# 1967 USGS STUDY - KEY FINDINGS


"Measurement of water levels in observation wells indicates that the water table slopes to the east."

"All neighborhood wells are located either upgradient or perpendicular to the gradient from the disposal site."

"There is, therefore, no possibility for any existing watertable wells to produce contaminated water."




### SITE CONCEPTUAL MODEL - 1967 SITE OPERATIONS







### 1978 USGS STUDY

- Evaluation of the extent and direction of leachate migration from the pesticide waste disposal site – (analytical testing for pesticides only)
- Hydrostratigraphic information from 5 WT and one deep (confined) well









# 1978 USGS STUDY - KEY FINDINGS


"Measurements of water levels in observation wells indicate groundwater moves toward the north and northwest."


"Several wells used for domestic water supplies are north and northwest of the disposal tract and are in the inferred path of leachate as it moves under natural gradients."



# 1979 RESPONSIBLE PARTY (RP) CONTRACTOR STUDY

- Developed an accurate water table contour map northerly GW flow
- Derived hydrostratigraphic information from residential wells, installed WT monitoring wells and from WT aquifer pump tests.







### 1979 RP CONTRACTORS STUDY - KEY FINDINGS


"Non-aqueous phase liquids (NAPLs) are present throughout the vadose zone of the disposal site."

"Significant groundwater contaminants are carbon tetrachloride and chloroform."

"Monitoring wells should not be installed in the artesian aquifer. The confining geologic formation protects that aquifer. **Monitoring wells** installed into this aquifer offer a potential avenue for contamination."



# SITE CONCEPTUAL MODEL 1978-1979 POST CLOSURE





# 1991 RP CONTRACTOR REMEDIAL INVESTIGATION (RI)

- Multimedia nature and extent contaminant evaluation
- Collected hydrostratigraphic information using hollow-stem auger and mud-rotary drilled boreholes/wells
- Mud-rotary was used for deeper boreholes/wells. Rig geologists logged mud-return cuttings to describe stratigraphy. They unknowingly drilled through the intermediate clay aquitard, which was logged as sand
- SCM revised to a single aquifer system based on RI logged wells
- Groundwater ingestion/inhalation showering cancer risk exceeded unity



### 1991 RP CONTRACTOR RI – KEY FINDINGS


"Confining clay
was not
encountered to a
depth of 223 ft bgs
(279 ft amsl) at
boring/well 1A."

"It became apparent that confining clay units beneath the study area are discontinuous and occur over a wide range of elevations."

"The hydrogeological investigation has shown that one hydrostratigraphic unit exists beneath the site. The aquifer consists of a fine sand with discontinuous layers and lenses of clay."




# PHASE 1 - PLUME DEVELOPMENT 1964-1991






### **SITE CONCEPTUAL MODEL - 1991 RI**






### SECOND-GENERATION RCRA CAP CONCEPTUAL SCHEMATIC





# **PUMP & TREAT 1997-2003**






# **PUMP & TREAT 1997-2003**

- Ten extraction wells
- Air stripping & GAC
- GAC off-gas treatment
- Treated ~772,000,000 gal
- Removed ~110,000 lbs VOCs
- Hydraulic capacity: 525 GPM
- Operated at 220 GPM (02/03)
   (~50 % of target rate)





# PHASE 2 - PUMP & TREAT 1997-2003





### 2006 TRUST CONTRACTOR SECOND 5-YEAR REVIEW STUDY

- Multimedia nature and extent contaminant evaluation
- Evaluated the hydraulic performance of the GW pump and treat system
- Collected hydrostratigraphic information from pump tests, borehole geophysics of existing wells and stratigraphic borings completed using sonic drilling methods
- Supported USEPA's remedy failure determination and update to the site's groundwater flow model



### **2006 SECOND 5-YEAR REVIEW - KEY FINDINGS**


"This five-year review has concluded that the components of the remedies for the site are not functioning as intended and that the remedies are not protective of human health and the environment."

"As a result of this (performance evaluation) and subsequent evaluations, it was determined that the site had a dual versus single aquifer system, which had appreciable negative impacts on the performance of the groundwater extraction and treatment system."



# **EM-31 GEOPHYSICAL TRENCH MAPPING**

- 3+ miles of drum trenches mapped
- Some trenches extended beyond edge of cap





# SONIC DRILLED STRATIGRAPHIC BORINGS











# WELL NEST 1A/1B




WT

aquifer




**Mud Rotary** 








# **SECOND 5-YEAR HYDROSTRATIGRAPHIC CROSS SECTION**





# SITE CONCEPTUAL MODEL - 2<sup>ND</sup> 5-YEAR REVIEW





# **SDA SVE PILOT TEST REMEDIATION 2009-2013**











### **SDA SVE PILOT TEST PERFORMANCE RESULTS**

### Mass of VOCs removed (lbs)







# **LANDFILL CAP UPGRADES 2015-2016**










# PHASE 3 - SDA SVE REMEDIATION PLUME IMPACT 2008-2017






# **SUMMARY & CONCLUSIONS**






# SITE CONCEPTUAL MODEL DEVELOPMENT TIMELINE





### SITE REMEDIATION TIMELINE



- Water line
- Two foot clay cap

### **2nd-generation remedy**


- Pump and treat
- RCRA cap

# **3rd-generation remedy**

- Cap upgrade
- Soil vapor extraction
- Groundwater TBD



# SITE PLUME EVOLUTION TIMELINE





# **THANK YOU**

**The Environmental Bankruptcy Trust** 

United States Environmental Protection Agency, Region IV

Tennessee Department of Environment and Conservation

Co-author

Justine Stumpf

**Team field and design staff** 

Scott Hayter Troy Wyss Doug Burge Beth Richter Bruce Kennington **Nestor Solar** Christa Cruikshank Gaines Barry Scott Tarmann **Tobias Parker** June Yeung Kevin Kyrias-Gann Abigail Wedig Angela DeDolph And many others Robert Coffman Cynthia Bonczkiewicz



# **QUESTIONS?**

The original inhabitants of this land had a saying – "Every time you take something from the Earth, you must give something back."



